SERVICE INFORMATION

LAND-ROVER



Vol.2 Issue 8

ROVER TRIUMPH BRITISH LEYLAND UK LIMITED SERVICE DEPARTMENT COVENTRY ENGLAND CV4 9DB

December, 1974

NUMERICAL INDEX TO SERVICE INFORMATION - Vol. 2 Issue No. 1 to 8

DIVISION	DESCRIPTION				MODEL	ISSUE	ITEM
00	Index for Service Information	W 40		(a. a)	All	7	13
00	Roller testing	2. 6:	* *	* *	AII	7	14
06	Oil filter torques				AII	5	8
07	Leather seals				All Series III	2	2
12	Engine pistons	2 D		8 6	AII	7	15
19	Altitude compensation for fuel injection	ction	pump		Series III, 21/4 litre diesel	1	1
19	Timing of D.P.A. injection pump		v •	* *	Series III, 21/4 litre diesel (Home Market)	1	1A
26	Engine anti-freeze	* *		A1180	AII	7	16
26	Thermostat	8. 8.			All 21/4 litre petrol	4	7
30	Exhaust manifold failures	× 3			Series III, 21/4 litre	5	9
	Main gearbox, transfer box, front output housing and				AII	2	3
	transmission brake - Overhaul		V 20		bonneted control		
37	Reverse gear 'jump -out'	* *	× (*)		All	3	5
51	Rear Salisbury axle flitch plate				Series III, 109	3	6
51	Rear Salisbury axle flitch plate	ec Tec	***	*01*3	Series III, 109	6	11
70	Preventative brake maintenance	*: 1*:	****	******	All	6	12
76	Door seals				All	2	4
76	Vehicle body height variation				AII	8	17
88	Instrument voltage stabiliser	212	2000	20020	AII	8 5	10

SERVICE INFORMATION

LAND-ROVER



December, 1974

ITEM 17

Division: 76

Subject: Vehicle body height variation

Models : All Land-Rover

Remarks :

Vol. 2 Issue 8

Because of recent enquiries into permissable body height variation on Land-Rover vehicles the procedure for checking and acceptable variations in height, which were the subject of an earlier type newsletter, are reproduced below:

With the vehicle in the static unladen condition standing on level ground measure the distance from the ground to the shackle pin centres, marked (A) and (B) Fig.2. The permissible variation between vehicle sides in front or rear suspension height is 1 in. (25 mm).

Problems have arisen occasionally with 'settling' of front or rear road springs; invariably the springs in question have been found to be within the required limits. It has been established that the apparent settling is generally a result of 'wind up' in the shackle bushes.

In these cases it is recommended that the following steps be taken before considering removal of the springs for investigation.

- Check the part numbers to ensure that the correct springs are fitted. The part number is stencilled on the top face and stamped on the under face of one of the leaves, see (A) Fig. 1.
- With the vehicle weight taken off the road springs, remove the shackle pins. If they
 are not a free fit in their mating threads or in the rubber bush inner sleeves, use
 emery cloth and oil the threads, or, if necessary, ream the holes through which the
 shackle pin passes.




Fig. 1. Spring identification

- Remove all traces of Parkerising from the ends of the inner faces of the shackle side plates.
- 4. Replace the shackle pins, and on achieving the spring position detailed in Fig.2, tighten first the shackle pin and then the lock nut to 70 lbf. ft. (9,6 mf.kg).
- 5. Allow the vehicle weight to be taken on the road springs.




Fig. 2. Presetting position of road springs to chassis frame

A-Shackle pin centre, front spring

B—Shackle pin centre, rear spring
C—3.500 in. (89 mm) 88 Bonneted Control models
D—3.750 in. (95 mm) 109 Bonneted Control models

E—4.250 in. (108 mm) Forward Control models F—5.000 in. (127 mm) 88 Bonneted Control models

G—6.000 in. (151 mm) 109 Bonneted Control models H—6.000 in. (151 mm) Forward Control models