

SB/GN/81 HOME

SEPTEMBER 1967

PRECAUTIONARY MEASURES
WHEN USING ELECTRIC-ARC WELDING
EQUIPMENT ON ALTERNATOR EQUIPPED
VEHICLES

Before using electric-arc welding equipment on alternator equipped vehicles, it is advisable to carry out the following precautionary measures:-

With Engine Stationary

1. Disconnect battery earthed cable.
2. Disconnect the main output and AL cables at the alternator.
3. Disconnect all cables at the 4TR control unit.

CAUTION

Reconnecting the cables is a reversal of the above procedure.
Ensure that all connexions are correctly remade.