

SB/GN/90 HOME

May 1968

MODIFIED FIELD TERMINAL ASSEMBLY FOR LUCARIZED GENERATORS

The field terminal assembly as fitted to Lucarized C40, C42 and C45 generators has recently been modified to eliminate the risk of the field terminal shorting to the yoke.

The part number of the modified terminal assembly is 54216878 and it will replace terminal assemblies 54211890 and 5421064.

To replace the original terminal assembly with the modified one, it may be necessary to lengthen the field coil leads. This can be done by carefully cutting the tape covering the coil until sufficient lead is exposed, and then retaping as necessary.

