



Service Department:

THE ROVER COMPANY LIMITED

By Appointment to
Her Majesty
Queen Elizabeth II



Manufacturers
of Motor Cars and
Land-Rovers

SOLIHULL
WARWICKSHIRE
ENGLAND

LAND-ROVER SERVICE NEWS LETTER No. 50

July, 1965

Item 248 SUBJECT: SERVICE LITERATURE

REMARKS:

We are repeatedly being advised by our Representatives that Land-Rover Service News Letters and other Service Literature are not being made available to Workshop and Stores personnel, who should be in possession of this important information on servicing Rover products.

Distributors and Dealers are urged to ensure that Rover Service Literature is adequately circulated or made accessible.

If you really require additional copies of our publications to achieve this, please notify The Rover Co. Ltd, Technical Service Department, Publication Section, Lode Lane, Solihull, Warwickshire, England.

Item 249 SUBJECT: AXLE DIFFERENTIAL, WARRANTY CLAIMS

MODELS:

Land-Rover.

PART NUMBER:

Differential complete 1 539732

REMARKS:

When submitting a Warranty Claim for differential units, Overseas Distributors must quote the identification number of the unit concerned. This number will be found stamped on the top periphery of the differential casing in one of the three following ranges.

Range	Letter or Figure representing month of manufacture	Year of manufacture	Identification	Four figure Unit number
'A'	E	65	—	7628
'B'	S	65	MG	2576
'C'	S	65	T	3608

Note 1 With effect from this date Warranty Claims for differential units will not be cleared for payment unless the above information is given.

Note 2 Do not confuse the differential unit number with the axle serial number which is stamped on the underside of the axle casing.

Item 250 SUBJECT: CLEANING RADIATOR

MODELS: All Land-Rovers.

REMARKS: Under certain operating conditions the radiator fins tend to become obstructed over a period of time, due to the accumulation of dirt, straw, insects etc.

It is necessary, therefore, occasionally to remove this foreign matter, to ensure that the radiator efficiency is not impaired.

Apply compressed air or water pressure from the rear, so forcing the foreign matter out through the front of the radiator. Never use a metal implement for this purpose, or serious damage may result to the radiator core.

Item 251 SUBJECT: OPTIONAL EQUIPMENT BOOK

MODELS: Land-Rover.

PART NUMBER: Optional equipment book 1 4437

REMARKS: The above publication has been revised and a general issue to all Distributors, Dealers and Fleet Users has been made by surface mail during the past week.

We particularly draw the attention of Fleet Users to this publication, as it contains items which protect the mechanical parts of vehicles operating under arduous conditions. The items which are of special interest are listed below:

Description	Kit Part Number
(a) Dust-proofed engine breather	517055
(b) Extra heavy duty road springs and shock absorbers	See Optional Equipment Parts Catalogue, Part Number 4705
(c) Gaiters for swivel pin housings	276954
(d) Grommet for propeller shaft	276484
(e) Mudshield for brake drums	528162 88
(f) Raised air intake	528163 109
(g) Reinforced front axle casing	517057
(h) Universal joint covers	501471
	261829

Items (a), (c), (d), (e), (f) and (h) are only obtainable through Distributors or Dealers.

Items (b) and (g) may also be obtained through Distributors or Dealers. Alternatively they may be obtained by quoting the appropriate 'E' number on the Sales Order as detailed below:

Item (b)

E.1003 88 models

E.1188 109 models

Item (g)

E.1123 88 RHD models

E.1124 88 LHD models

E.1125 109 RHD models

E.1126 109 LHD models