

Mr C. G. Baker
Sydney



Service Department.

THE ROVER COMPANY LIMITED



SOLIHULL
WARWICKSHIRE
ENGLAND

LAND-ROVER SERVICE NEWS LETTER Vol. 2 No. 18

March 1967

Item 72 SUBJECT: **SERVICE ORGANISATION (Policy Item)**


REMARKS:

Whilst in the past it has not been our practice to issue to our Distributors and Dealers Organisation Charts, certain changes have recently been made in the Service Division and it is felt that this would be an opportune time for such a chart to be made available.

The current Organisation Chart is therefore reproduced with this News Letter and it is felt appropriate to explain that, whilst the new appointments which are shown have already taken place, certain of these are, of course, based upon the retirement of Mr. F. G. Hawkins later this year, following his long service with the Company as Technical Service Manager.

The arrangements in respect of London and Coventry Service Stations are not shown.

ROVER SERVICE DIVISION, SOLIHULL AND CARDIFF



Item 73 SUBJECT: **HEADLAMPS**

MODELS: Land-Rover, Series I, II and IIA.

MODIFICATIONS: Following the Lucas policy of lamp standardisation for F700 type headlamps, whereby a headlamp less rim and body gaskets is supplied in place of the headlamp complete, new Rover part numbers have been introduced to cover lamps supplied in this condition.

A chart giving full details is available on application to The Rover Company Limited, Technical Service Department, Lode Lane, Solihull, Warwickshire.