# Service Bulletin

## JOSEPH LUCAS (SALES & SERVICE) LTD. GREAT HAMPTON STREET BIRMINGHAM 18

SB/IG/102 HOME

JUNE 1968

#### IGNITION COILS

#### MODELS HP12 AND 11P12

#### CORRECTION OF PART NUMBERS

### (AS LISTED IN SB/IG/101 AND D/7)

Please note that the part numbers of the 11P12 and HP12 ignition coils, listed in SB/IG/101 and D/7, Page 2, should be amended, as follows:-

MODEL	PART NO.	DESIGNED TO REPLACE
11P12	45213	llCl2, LAl2
HP12	45212	HA12, PA12

Would you please correct any copies of SB/IG/101 or D/7 in your possession.