

SB/SW/41

May 1968

REPLACEMENT OF STARTER SOLENOID
MODEL 2ST PART NO. 76445, USED ON
JAGUAR AUTOMATIC TRANSMISSION MODELS

Starter solenoid, Model 2ST Part No. 76445, has a flexible rubber cap. When this solenoid is used on Jaguar Automatic Transmission models, a brass cap, Part No. 54337061, is fitted on the end of the solenoid. This is a safety measure, to prevent the car from being started from under the bonnet.

Starter solenoid 2ST 76445 has now been replaced by 4ST 76766. This also has a flexible cap. Further, it is not possible to fit brass cap 54337061 on this solenoid. When a service replacement for solenoid 2ST 76445 is required for Jaguar Automatic Transmission models, Solenoid Model 4ST Part No. 76772 should be ordered, as this has a hard plastic cap, and its use will prevent the car from being started from under the bonnet.