

91906

SOLIHULL, WARWICKSHIRE, England
Telephone No.: Sheldon 4242
Telegrams: Rovrepair, Solihull
Telex No.: 33-156

Rover Service News Letter No. 102A

March, 1959

TO ALL HOME DISTRIBUTORS AND DEALERS

Dear Sirs,

This special News Letter is being circulated to give advance information to Home Distributors and Dealers only on Land-Rover chassis frame reconditioning.

SECTION II

WORKSHOP AND PARTS INFORMATION

Item 1 SUBJECT:

CHASSIS FRAME RECONDITIONING

MODELS: 1948-59 Land-Rover.

PART NUMBERS:	Chassis frame 1	233181	1948-50 80 models	1½ in. spring bracket
	Chassis frame 1	236805	1950-53 80 models	2¼ in. spring bracket
	Chassis frame 1	264749	1954-55 86 models	
	Chassis frame 1	246522	1954-55 107 models	
	Chassis frame 1	269430	1956-58 88 Series I models	
	Chassis frame 1	269431	1956-58 109 Series I models	
	Chassis frame 1	269454	1955-58 107 Station Wagon	
	Chassis frame 1	278666	1958-59 88 Series II models	
	Chassis frame 1	278664	1958-59 109 Series II models	
	Chassis frame 1	278665	1958-59 109 Station Wagon	

REMARKS:

It has been decided to introduce a "Flat Rate" Exchange Price for Land-Rover chassis frames, and our existing scheme of reconditioning customers' individual chassis frames will therefore be discontinued. The date of introduction will be 4th May 1959, and all Land-Rover chassis frames received at the factory after that date will be dealt with under the new system.

The Exchange Price will be £35 0s. 0d., subject to "normal" discount.

It is important to note that the Exchange Price should not be quoted for chassis frames which are obviously scrap and that the acceptance of any chassis frame by the factory is dependent upon its being suitable for reconditioning.

Yours faithfully,
for THE ROVER COMPANY LIMITED,

M. Brewer.

Publications Editor,
Technical Service Department.