



Service Department:

THE ROVER COMPANY LIMITED

SOLIHULL
WARWICKSHIRE
ENGLAND

LAND-ROVER SERVICE NEWS LETTER
No. 18

January, 1962

- Item 91** SUBJECT: **WHEEL WOBBLE**
 MODELS: All Land-Rover.
 REMARKS: In Land-Rover News Letter No. 8, item 48, we gave considerable information on the checks which should be made in cases of steering kick or wheel wobble on the Land-Rover. Further investigation into this matter indicates that cases of wheel wobble may be caused because proper mating of the cone and the cone seat in the swivel pin damping mechanism is not taking place. We recommend, therefore, that in any difficult case of wheel wobble a check is carried out, with the use of blue marking, to ensure proper contact is made over the whole of the working surface of each cone and cone seat. If a good contact is not being made, the offending high spots may be removed by hand scraping.
- Item 92** SUBJECT: **SWIVEL PIN HOUSING STUD CONVERSION**
 MODELS: Land-Rover Series II and IIA. With non-pendant ball joints.
 PART NUMBER: Swivel pin housing stud conversion kit 1 532329
 REMARKS: A swivel pin housing stud conversion kit, complete with detailed fitting instructions, is now available from our Parts Department. The kit may be used when it is considered desirable to replace the $\frac{3}{8}$ in. (9,5 mm) studs in the swivel pin housing with the later $\frac{7}{16}$ in. (12 mm) type. This modification should only be necessary on vehicles with non-pendant ball joints.
- Item 93** SUBJECT: **MUDSHIELDS FOR BRAKE DRUMS**
 MODELS: Land-Rover Series II and IIA.
 PART NUMBERS: Mudshields for brake drum 1 528162 '88'
 Mudshields for brake drum 1 528163 '109'
 REMARKS: Please note that Part Numbers 528162 and 528163 represent one complete kit of parts comprising four mudshields and fixings, and should therefore be ordered as 1 off per vehicle for either '88' or '109' models as required and not at 4 off per vehicle as detailed in Land-Rover News Letter, No. 14, Item 70.
- Item 94** SUBJECT: **FLASHING INDICATORS**
 MODEL: Land-Rover Series IIA.
 PART NUMBER: Flashing indicator kit 1 531945
 REMARKS: A flashing indicator kit, complete with detailed fitting instructions, is now available from our Parts Department. It is applicable only to the Series IIA model.

Item 95 SUBJECT: **RADIO SUPPRESSOR KIT**

MODEL: Land-Rover Series IIA.

PART NUMBERS: Radio suppressor kit 1 531949 Diesel
Radio suppressor kit 1 531951 Petrol

REMARKS: Radio suppressor kits, complete with detailed fitting instructions, are now available from our Parts Department for both Diesel and Petrol Land-Rover Series IIA models as applicable.