



Service Department:

THE ROVER COMPANY LIMITED

By Appointment to
Her Majesty
Queen Elizabeth II



Manufacturers
of Motor Cars and
Land-Rovers

SOLIHULL
WARWICKSHIRE
ENGLAND

LAND-ROVER SERVICE NEWS LETTER No. 37

August 1963

Item 183 SUBJECT: CARBURETTER

MODELS: Land-Rover Series IIA 2¼ Litre Petrol.

PART NUMBERS:	Carburetter, Solex 40PA 10-5A	1	546029
	Carburetter, with heater element, Solex B40PA 10-6	1	546180
	Choke tube, Solex 50459/2/26	1	542638
	Main jet, Solex 50552/6/120	1	542639
	Pump jet, Solex 52200/50	1	542640
	Jet air bleed, blank, Solex 13334	1	542641

REMARKS: The carburetters with modified settings are completely interchangeable, as applicable, with the earlier type carburetters fitted to Land-Rover Series IIA Petrol Models. They have been introduced to improve the low speed torque characteristics of the 2¼ litre petrol engine and can be identified by a brass tag under one of the float chamber cover fixing bolts.

Full details of a carburetter conversion kit for earlier 2¼ litre petrol models will be found in Land-Rover Service News Letter No. 35, Item 176.