

of. a. bolts
of p.m.c.



Service Department:

THE ROVER COMPANY LIMITED



SOLIHULL
WARWICKSHIRE
ENGLAND

LAND-ROVER SERVICE NEWS LETTER Vol. 2 No. 19

April 1967

Item 74 SUBJECT: **APPROVED LUBRICANT (Policy item)**
 MODELS: Land-Rover 88 Regular and 109 Long with rear Powr-Lok differential.
 REMARKS: Please note that Fina Pontonic Plus oil is approved for use in the above models.

Item 75 SUBJECT: **ENGINE**
 MODELS: Land-Rover 88 Regular, 109 Long and 110 Forward Control with 2¼ litre petrol engine.
 MODIFICATION: Introduction of modified rocker shaft brackets for use with shorter set bolts.
 LITERATURE AFFECTED: Land-Rover Parts Catalogue, Part No. 4656, page 57.
 The new parts are already listed in the Forward Control Parts Catalogue, Part No. 4862.
 PART NUMBERS: Rocker shaft bracket 5 554602
 Set bolt (½ in. UNF x 4.125 in. long) 5 554621
 COMMENCING NUMBERS: 88 Regular and 109 Long: engines from suffix letter 'J' onwards.
 110 Forward Control: engines from suffix letter 'A' onwards.
 REMARKS: The new rocker shaft brackets are not interchangeable individually, but they can be used on early engines, provided they are fitted in complete sets. The tightening torque for the shorter bolts has not been altered.

Item 76 SUBJECT: **PRESTOLITE ALTERNATOR**
 MODELS: Land-Rover.
 REMARKS: Since the introduction of the 12-volt negative earth Prestolite alternator, the number of vehicles fitted with this equipment has increased substantially, particularly vehicles operated by fleet users.
 Rover Distributors and Dealers are reminded of their responsibility to provide service and to maintain an adequate stock of spare parts for these vehicles.
 Full spare parts information will be found in Amendment No. 1 to the Land-Rover Optional Equipment Parts Catalogue, Part No. 4705, and an appropriate stock of spare parts should be ordered from our Parts Department at Cardiff.
 A Workshop procedure leaflet, Part No. 605166, which also includes information on testing the equipment, is available on request to The Rover Company Limited, Service Department, Solihull, Warwickshire, England. English version only.

- Item 77** SUBJECT: **OVERHAUL KITS**
- MODELS: All Land-Rovers.
- REMARKS: When overhauling brake and clutch cylinders using the repair kits available for this purpose, it is important that the components are lubricated in accordance with the manufacturers' instructions and, where applicable, using the lubricant provided in the kit, to ensure protection for rubber seals and boots.