



Service Department:

THE ROVER COMPANY LIMITED



By Appointment to
Her Majesty
Queen Elizabeth II

Manufacturers
of Motor Cars and
Land-Rovers

SOLIHULL
WARWICKSHIRE
ENGLAND

LAND-ROVER SERVICE NEWS LETTER Vol. 2 No. 29

February, 1968

Item 134 SUBJECT: HEATER (Policy item)

MODELS: Series II and IIA Land-Rover, Bonneted Control, except 109 in. 2.6 litre 6 cylinder.
Series IIA and IIB Forward Control Land-Rover.

PART NUMBERS: Radiator for vehicle heater 1 601506 Part of heater
Part No. 307838

REMARKS: Our attention has been drawn to the increasing number of complete heaters returned to us under Warranty, which have been found to be leaking.
It appears that Distributors and Dealers are not aware that the radiator where the leak actually occurs, is available as a separate item from our Parts Department. It must be noted that as from the date of this News Letter claims will **not** be accepted for complete heaters returned to us under Warranty, which are only suffering from a leaking radiator.

Item 135 SUBJECT: BRAKES

MODELS: Land-Rover 88 Bonneted Control.

MODIFICATION: Introduction of a 'C.V.' type brake master cylinder in place of the 'C.B.' used previously. This change also involves new reshaped brake pipes.

LITERATURE
AFFECTED: Land-Rover Parts Catalogue Part No. 4656, pages 221, 243 and 245.
Land-Rover Workshop Manual Part No. 4611, Operation H.12 and H.16.

PART NUMBERS: Brake master cylinder 1 569126
Pipe complete, master cylinder to 5-way junction .. 1 564786 RH Stg.
Pipe complete, master cylinder to 5-way junction .. 1 564783 LH Stg.
Pipe complete, supply tank to master cylinder .. 1 564785 RH Stg.
Pipe complete, supply tank to master cylinder .. 1 564784 LH Stg.
Pipe complete clutch master cylinder to hose .. 1 568857 LH Stg.
Pipe complete, reservoir to master cylinder .. 1 564926 LH Stg.
Overhaul kit for brake master cylinder 1 605642

COMMENCING
NUMBERS: Vehicle serial numbers:
Land-Rover 88 in. Petrol Bonneted Control model from 24131337D onwards.
Land-Rover 88 in. Diesel Bonneted Control models from 27108694D onwards.

REMARKS: Early and late type brake master cylinders are not interchangeable as individual items and both types must be stocked for service replacements. If it is desired to fit the latest C.V. type master cylinder to earlier models, then brake master cylinder and brake pipes as appropriate must be supplied and fitted.

Item 136 SUBJECT: HARD TOP

MODELS: Land-Rover 88 and 109 in. Bonneted Control.

LITERATURE AFFECTED: See Cumulative Amendment No. 2 to Land-Rover Optional Equipment Parts Catalogue, Part No. 605159, pages 199, 207 and 215.

PART NUMBERS:	Hard top assembly plain sides	1	320653	88 in.
	Hard top assembly, fixed side windows	1	320654	88 in.
	Hard top assembly, sliding windows	1	320657	} Export only
	Hard top assembly, plain sides	1	320655	
	Hard top assembly, fixed side windows	1	320656	109 in. Export only

REMARKS: Many of our Distributors and Dealers do not appear to be aware that the above hard top assemblies do not include the rear lid. When ordering any of the above assemblies, the rear lid, or rear door kit assembly must be ordered separately as required.

Part numbers are:

Rear lid complete assembly	320652
Rear door kit complete assembly	516473 or 320613 as applicable