

Land-Rover Service Newsletter Vol. 3 No. 18



November 1970

The Rover Company Limited Service Department: Solihull, Warwickshire, England

By Appointment to
Her Majesty
Queen Elizabeth II



Manufacturers
of Motor Cars and
Land-Rovers

Item 124 SUBJECT: STEERING ROD CLIP

MODELS: Land-Rover, Range Rover.

MODIFICATION: Introduction of new ball joint clip and addition of slots in all steering linkage tubes.

PART NUMBERS: Clip, steering rod 2 577898

REMARKS: The new clip is now manufactured from improved material to prevent distortion. To increase the efficiency of the clamping at the steering tube ends, an additional slot is added diametrically opposite the existing slot.

The part numbers for the various rods, i.e. steering drag link, track rod and longitudinal steering tube, remain unchanged, and the latest type will be supplied for all Service replacements.