

Land-Rover Service Newsletter Vol. 3 No. 21



February 1971

The Rover Company Limited Service Department: Solihull, Warwickshire, England

By Appointment to
Her Majesty
Queen Elizabeth II



Manufacturers
of Motor Cars and
Land-Rovers

Item 129 SUBJECT: FAN BLADES

MODEL: Land-Rover 2 $\frac{1}{4}$ litre Diesel.

MODIFICATION: Re-introduction of the 4-bladed fan in place of the 5-bladed type, which was fitted as a temporary measure with 'Morris' type radiator blocks.

PART NUMBERS: 5-bladed fan (temporary measure) September 1969 to March 1970

Fan assembly	1	574044
Distance piece for fan	1	564298
Set bolts ($\frac{1}{4}$ in. UNF x $\frac{3}{8}$ in. long)	4	256202
Fan belt	1	GFB 124

4-bladed fan (re-introduced) March 1970

Fan assembly	1	515090
Set bolt ($\frac{1}{4}$ in. UNF x $\frac{3}{4}$ in. long)	4	255207
Fan belt	1	GFB 124

COMMENCING NUMBERS: 5-bladed fan commenced from engine number 27160408K.
Re-introduced 4-bladed fan commenced from engine number 27165959K.

REMARKS: To avoid a certain amount of confusion that may have arisen, it should be noted that as a temporary measure in September 1969 to overcome overheating problems encountered under certain conditions on Land-Rover 2 $\frac{1}{4}$ litre Diesel models, which were fitted with the 'Morris' type radiator block, Part No. 577609, a 5-bladed fan as used on the Land-Rover 6-cylinder Petrol models, was fitted to replace the 4-bladed type.

Consequent radiator design improvements led to the re-introduction of the 4-bladed fan in March 1970.

Item 130 SUBJECT: TRANSMISSION BRAKE

MODELS: Land-Rover Series II and IIA Bonneted and Forward Control.
Series IIB Forward Control.

MODIFICATION: Replacement of lining kit, Part No. 541994, by individual components to accommodate brake shoes with 8 and 10 holes.

PART NUMBERS:	Lining for transmission brake shoe	} 10-hole type	2	607249
	Rivet for lining		20	607250
	Lining for transmission brake shoe	} 8-hole type	2	607251
	Rivet for lining		16	607252

REMARKS: Distributors and Dealers are requested to advise the personnel concerned and to amend parts records to suit.

Item 131 SUBJECT: SERVICE LITERATURE

MODELS: Land-Rover Series I and IIA.

REMARKS: All stocks of the publications listed below will be disposed of on July 1st 1971. We are therefore offering these publications on a free-of-charge basis to all recipients of News Letters, but their account will be debited with the cost for package and postage. All requests for this literature should be made to our Parts Department at Cardiff as soon as possible.

Part No.	Description	Model
4041	Instruction Manual, English ..	1955
4173	Instruction Manual, Diesel, French	1957/58
4197	Instruction Manual, Spanish ..	1958 109 in. Series II Petrol
4206	Instruction Manual, French ..	Series II Diesel
4207	Instruction Manual, German ..	Series II Diesel
4208	Instruction Manual, Spanish ..	Series II Diesel
4216	Instruction Manual, French ..	Series II Petrol
4490	Literature Pack, German ..	Series IIA including Forward Control
4492	Literature Pack, Portuguese ..	Series IIA including Forward Control

Item 132 SUBJECT: SERVICE LITERATURE

MODELS: Land-Rover Series II and IIA.

PART NUMBERS:	Workshop Manual, French Part I	606409
	Workshop Manual, French, Part II	606410
	Workshop Manual, German, Part I	606411
	Workshop Manual, German, Part II	606412
	Workshop Manual, Spanish, Part 1	606413
	Workshop Manual, Spanish, Part II	606414

REMARKS: Stocks of the above Workshop Manuals are available from our Parts Department. Copies should be ordered directly as required.