

Land-Rover Service Newsletter Vol. 3 No. 23



May 1971

The Rover Company Limited Service Department: Solihull, Warwickshire, England

By Appointment to
Her Majesty
Queen Elizabeth II



Manufacturers
of Motor Cars and
Land-Rovers

- Item 138** SUBJECT: **PARTS IDENTIFICATION (Policy item)**
- MODELS: All Land-Rovers.
- REMARKS: It has been brought to our attention that certain vehicle manufacturers utilise casting and forging numbers on components as part numbers. This does not apply to Rover products and the use of casting or forging numbers when ordering parts will only cause confusion and delay.
- Distributors and Dealers are requested to advise all members of their staffs who may be involved that to obtain the correct part number for a Rover component the appropriate Parts Catalogue or P.C.M.I. transparency should be referred to and only the part number given therein quoted in orders submitted to the Parts Division.
-
- Item 139** SUBJECT: **GEAR SELECTOR SHAFT**
- MODELS: All Land-Rovers, Bonneted Control and Forward Control.
- MODIFICATION: Introduction of spring pin for 1st and 2nd gear selector shaft, replacing the peg previously used, to provide improved tolerance conditions.
- P.C.M.I.
TRANSPARENCY: The information detailed in this item is incorporated in the appropriate transparency.
- LITERATURE
AFFECTED: Land-Rover Forward Control Parts Catalogue, Part No. 4862, page 143.
- PART NUMBER: Spring pin fixing interlocking pin 1 571145
- REMARKS: Spring pin and peg are not interchangeable and both items must be stocked for all service replacements.
-
- Item 140** SUBJECT: **REVISED GEAR LEVER**
- MODEL: Land-Rover, Bonneted Control.
- MODIFICATION: Replacement of 'O' ring by 'polyurethane' bonded to ball of gear lever to reduce the possibility of gear lever rattles. New sliding knob introduced.

P.C.M.I.

TRANSPARENCY: The information detailed in this item will be incorporated in the next available transparency.

LITERATURE

AFFECTED: Land Rover Parts Catalogue, Part No. 605957, page 249.
Land-Rover Workshop Manual, Part I, Part No. 606407, Operation C1-11.

PART NUMBERS: Main gear change lever assembly 1 576311 R.H.Stg. } 4 cylinder
Main gear change lever assembly 1 576312 L.H.Stg. } models
Main gear change lever assembly 1 576578 R.H.Stg. } 6 cylinder
Main gear change lever assembly 1 576579 L.H.Stg. } models
Gear change lever 1 571666 R.H.Stg. } 4 cylinder models. Part
Gear change lever 1 571667 L.H.Stg. } of 576311 and 576312
Gear change lever 1 576576 R.H.Stg. } 6 cylinder models. Part
Gear change lever 1 576577 L.H.Stg. } of 576578 and 576579
Knob for gear lever 1 576316 } Part of 576311, 576312, 576578,
Star tolerance ring 1 571661 } 576579

REMARKS: Complete gear change levers are interchangeable but where a replacement knob is required for an early lever, star tolerance ring, Part No. 571661, and sliding type knob, Part No. 576316, must also be supplied and fitted. When stocks of the early parts are exhausted, the new items will be supplied for all Service replacements. Distributors and Dealers are requested to amend the literature in their possession accordingly. The literature affected will be revised at the next available reprint.

Item 141 SUBJECT: HUB LUBRICATION

MODIFICATION: Introduction of revised hub lubrication procedure.

MODELS: All Land-Rovers.

LITERATURE

AFFECTED: Land Rover Workshop Manual, Part 2, Part No. 606408.
Operation E1-1 and F1-1.

REMARKS: When lubricating front and rear hubs, only the bearing should be packed with grease, and not the hub itself.
Distributors and Dealers are requested to instruct the personnel concerned accordingly, and to amend their records to suit.
The literature affected will be amended at the next available reprint.