



Service Department:

**THE ROVER COMPANY LIMITED**

SOLIHULL  
WARWICKSHIRE  
ENGLAND

LAND-ROVER SERVICE NEWS LETTER  
No. 28

September 1960

With effect from September 19th 1960, it will be the policy of the Service Department to supply crankshaft main bearings, connecting rod bearings and crankshaft thrust washers in boxed pairs.

The complete list of replaced and new part numbers are detailed below: Existing stocks can be used under the original part number or paired and stocked under the new number.

Distributors and Dealers are especially requested to make immediate alteration to their records and usage figures.

Individual bearing part number	Paired bearing part number	Year and model	Individual bearing part number	Paired bearing part number	Year and model	
237273	523277	} 1948-54 Land-Rover	248747	523336	} Land-Rover 2 Litre Diesel models (Standard only)	
237926	523278		248748	523337		
237928	523279		248749	523338		} Land-Rover 2½ Litre Petrol models
237929	523280		248750	523339		
			248751	523340		
239824	523311	} 1955-58 Land-Rover 2 Litre Petrol models	248782	523331	} Land-Rover 2 Litre Diesel models	
239825	523312		248783	523332		
239826	523313		248784	523333	} Land-Rover 2½ Litre Petrol models	
239827	523314		248785	523334		
239828	523315		248786	523335		
239829	523306		276857	523321	} Land-Rover 2 Litre Diesel models (Standard only)	
239830	523307		276858	523322		
239831	523308		276859	523323		
239832	523309		276860	523324		
239833	523310		276861	523325		
239834	523301		502131	} 523326		} Land-Rover 2 Litre Diesel models (Standard only)
239835	523302		502136			
239836	523303		502132	} 523327		} Land-Rover 2½ Litre Petrol models
239837	523304		502137			
239838	523305		502133	} 523328		
239839	523316		502138			
239840	523317		502134	} 523329		
239841	523318	502139				
239842	523319	502135	} 523330			
240386	523320	502140				