



Service Department:

THE ROVER COMPANY LIMITED

By Appointment to
Her Majesty
Queen Elizabeth II



Manufacturers
of Motor Cars and
Land-Rovers

SOLIHULL
WARWICKSHIRE
ENGLAND

LAND-ROVER SERVICE NEWS LETTER Vol.2 No.5

Item 13 SUBJECT: **STOCK TRAYS**

January, 1966

PART NUMBERS:	Cardboard stock tray, 2 in. (50 mm) wide	601578
	Cardboard stock tray, 4 in. (100 mm) wide	601579
	Cardboard stock tray, 6 in. (150 mm) wide	601580

REMARKS: Our Parts Department now have available a range of inexpensive stock trays for binning small and not so small stock items. They can be used on shelves or to subdivide larger bins and we feel they will be of great interest to our Distributors and Dealers.

Advantages are:

- Low initial cost combined with adequate strength.
- Can be stored flat in minimum space when not in use.
- Creased for easy folding.
- Assembled in seconds. (See Fig. 1).
- Part number and description easily affixed to end of tray.
- Enables any available space to be utilised for storage purposes.




Fig. 1. Folding cardboard stock tray

- 1—Fold outer end flaps upwards in direction of arrows
- 2—Bend side flaps and centre end flaps upwards
- 3—Bend end flaps up and over and into slots at bottom of tray

Distributors and Dealers should order these parts on their normal stock order.

Minimum quantity ten (10) of any one size.

Please note the cardboard stock trays are not recommended for parts which are protected with a thick layer of oil.

PRICE:	Part number				
	601578	4d. nett
	601579	5d. nett
	601580	6d. nett

Item 14 SUBJECT: **EXCHANGE PARTS (Policy item)**

MODELS: All.

REMARKS: With effect from February 1st, 1966, the following flywheels will no longer be accepted under the Rover Exchange Parts Scheme.

FLYWHEEL

Part No. New	Part No. Reconditioned
230304	277339
247167	512392
247991	530514
272661	530513
505667	530515
516082	524638
524884	530516
530912	538164
536882	600244
538195	600545
538221	538324
541760	600537
546518	600979
546519	549544
554681	601472
600243	600540

Stocks of new flywheels and flywheel ring gears as applicable are still available from our Parts Department.

For those Distributors and Dealers who have the facilities for reconditioning flywheels, details of machining limits and ring gear part numbers, etc. will be found in Land-Rover Service News Letters Nos. 15 and 43.

Item 15 SUBJECT: **RECOMMENDED LUBRICANTS (Policy item)**

MODELS: Land-Rover.

REMARKS: Please note that Mobiloil Special SAE 20W/40 is officially approved by the Rover Company for use in Land-Rover models for the applicability and range of SAE numbers it covers as detailed in our Service Literature.