



*Service Department:*

**THE ROVER COMPANY LIMITED**

By Appointment to  
Her Majesty  
Queen Elizabeth II



Manufacturers  
of Motor Cars and  
Land-Rovers

SOLIHULL  
WARWICKSHIRE  
ENGLAND

**LAND-ROVER SERVICE NEWS LETTER Vol. 2 No. 7**

March, 1966  
(Issued mid-February)

- Item 22** SUBJECT: **RECOMMENDED LUBRICANTS (Policy Item)**
- MODELS: Land-Rover.
- REMARKS: Duckhams 20/50 Motor Oil is officially recommended by the Rover Company for use in our products in lieu of Duckhams NOL Twenty as detailed in our Service Literature. This information will be incorporated in the various publications as and when they are re-printed.
- 
- Item 23** SUBJECT: **ALTERNATOR**
- MODELS: Land-Rover Series IIA 88 Regular and 109 Long, 88 and 109 Station Wagon, Petrol and Diesel.
- REMARKS: In Land-Rover Service News Letter, Vol. 2, No. 4, Item 10, we detailed information about the new Prestolite alternator.
- A Workshop Procedure Leaflet covering this equipment is now available. Copies can be obtained from the Rover Company Limited, Technical Service Department, Solihull, Warwickshire, England, under Part No. 4759. English version only.